


# OSP Cabinet Replacement Fans & Alarm Control Boards



INSIDE VIEW OF 80A/D CABINET



## "Lucent 2B / 2C"

**PN # TF-LU2B**

48 Volt Replacement Fan for  
**Lucent 2B Fan Tray**

w/ 3 Wire Plug

(Equiv. to KS22501L5A)

**NEW** Alarm Control Boards are also available,  
order # **TFC-LU2BC-01, MAT # 1458909**



**LUCENT 2B FAN TRAY**  
w/ (3) EXISTING FANS (BOTTOM VIEW)  
(fan tray is not included)

### Ordering Information:

**MAT #**

TF-LU2B	48V Fan for Lucent <b>2B</b> Fan Tray w/ 3 Wire Plug (Equiv. to KS22501L5A)	1336049
TF-LU2C	48V Fan for Lucent <b>2C</b> Fan Tray w/ 3 Wire Plug (Equiv. to KS22501L5A) - (not shown)	1336060
TFC-LU2BC-01	Alarm Control Board for Lucent <b>2B</b> & <b>2C</b> Fan Trays (customer supplied fan trays)	1458909
TFCS-2BPWRY-01	Power Cable "Y" for Lucent <b>2B</b> & <b>2C</b> Fan Trays w/ 1 Male Connector to Female "Y", (1) - (not shown)	
TFCS-2BRS-08	Remote Sensing Daisy Chain Cable for Lucent <b>2B</b> & <b>2C</b> Fan Trays w/ 2 Wires & Connectors, (8') - (not shown)	

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**