



Mesa 768 Cabinet Solutions for Brightspeed

New Heat Exchanger Replacements

**MOUNTING BRACKET
LOCATED ON THE ROOF
OF THE CABINET**



(133mm)



TAG # TF-MC133-02

(NEW 133mm
Heat Exchanger)


**Brightspeed SAP MAT #
1355448**

**(1) IN EACH
CABINET**

**TAG Inc. - (REPAIRS)
MARCONI / RELTEC / TELLABS
POWER CONTROL UNITS (PCU's)**



MESA 768 CABINET (FRONT VIEW)



MESA 768 CABINET (INSIDE - FRONT VIEW)



- Trace Circuitry Testing & Repair
- Component Testing & Replacement

For more Information,

**Please Call:
856-753-8585**

**or Email:
custsvcs@tagcords.com**

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645

Ordering Information:

TF-MC133-02

**Brightspeed SAP MAT #
1355448**

**(133mm) Heat Exchanger for Mesa 768 Cabinets
w/ 3 Pin Plug**
(fan only - use with existing mounting bracket)

(133mm)

