


Alcatel (1000 / 7300 / DSC ECS1 / 1603)* Replacement Fans

"Alcatel 1000 / 7300"


PN # TF-ALC-01

48V Replacement Fan for
Alcatel 1000 / 7300 Fan Tray
w/ Tach Output & 3 Wire Plug

(use in **3EC 15478** (XXXX),
3EC 37933 (XXXX) &
3EC 36760 (XXXX) Fan Trays)



**Brightspeed SAP MAT #
1337633**



"Alcatel 7300"

PN # TF-AL7300-02

48V Replacement Fan for
Alcatel 7300 Fan Tray
w/ Internal Sensor, Tach Output & 3 Wire Plug
(use in **3EC 16697** (XXXX) Fan Trays)


MAT # 1341521

"DSC / Alcatel ECS1"

PN # TF-DSCECS1-01

48V Replacement Fan for
DSC / Alcatel ECS1 Fan Tray
w/ 3 Wire Plug

MAT # 1341522




"Alcatel 1603"

PN # TF-ALC1603-01

48V Replacement Fan for
Alcatel 1603 Low-Volume Fan Tray
w/ 3 Wire Plug

**Brightspeed SAP MAT #
1475327**



625052-000-0XX (w/ 4 EXISTING FANS)
(fan tray is not included)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax : (856) 768-7645

Telecom Assistance Group