

DMS-100 / DMS-10 / Carrier VoIP Replacement Fans

"DMS-100"



Brightspeed SAP MAT #
1349234

PN # TF-DMS-NTRX91
DMS-100, 48 Volt Replacement Fan
w/ 3 Wire Plug

(use in NTRX91AA / NT0X91AA fan units)
(MVIE and CSDM bays), CLEI: ENMYACM


"DMS-10"



Brightspeed SAP MAT #
1341506

PN # TF-DMS10-01
DMS-10, 48 Volt Replacement Fan
w/ Power Prongs

(fan only,
use with existing mounting bracket)



MAT # 1341507

(fan only,
arm assembly
is not included)

"Nortel IW SPM-IP"

PN # TF-DMS-FOS
Nortel IW SPM-IP
48 Volt Replacement Fan

(use in NTLX56AA fan assemblies,
found in Nortel IW SPM-IP NTLX55AA cooling units)

"Media Gateway 9000"

PN # TF-MG9K-01
Nortel / GENBAND Media Gateway 9000
48 Volt Replacement Fan
w/ 3 Wire Plug

(use in NTTY18AA Cooling Unit)



MAT # 1359401



150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group