
DMS-100 Dual-Scroll Blower Replacement Unit




► <u>NEW</u> Drop-in Replacement

DMS-100 DUAL-SCROLL REPLACEMENT BLOWERS

(used in NT9X950 "w/ hanging blowers" (replaces # A0383325 & A0381714))

(Commonly found in DPCC / LIM / ENET bays)



NT9X950 HAS (3) BLOWER UNITS PER BAY

Ordering Information:

Brightspeed MAT #

TF-DMSMCL-02 DMS-100 Dual-Scroll Blower Replacement Unit

1490298

w/ (1) 4 pin plug & (1) 3 pin plug

includes (1) 3 pin adapter cable (# TFCS-DMSMCL3) (used in NT9X950 "w/ hanging blowers" (replaces # A0383325 & A0381714)) (commonly found in DPCC / LIM / ENET bays)

TFC-DMSAPW-3 Alarm Board for DMS LIM/ENET Blower - (not shown)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 Telephone: (856) 753-8585

Fax: (856) 768-7645

Telecom Assistance Group

www.tagcords.com