



| REPAIR VENDOR #  | REFURBISHMENT DESCRIPTION<br>(New TAG Fans, New TAG Alarm Boards are Installed - New Switches, Connectors & Hardware are Supplied As Needed) | PICTURE   |
|------------------|--|---|
| 1 TFR-ALC1000-01 | Alcatel 1000 ADSL Fan Tray<br>PN 3EC15478<br>(HECI: VAMYAAMGAA) <b>ALCATEL 1000</b>  |    |
| 2 TFR-ALC7330-01 | Alcatel 7330 VRAD<br>(HECI: VAPQAFZFxx)<br>(3FE 24322 (XXXX)) <b>7330 VRAD</b>   |   |
| 3 TFR-LU2A-01    | 2A Lucent Fan Tray <b>LUCENT 2A</b>  |  |
| 4 TFR-LU2B-01    | 2B Lucent Fan Tray<br>(COMCODE: 105550420) <b>LUCENT 2B</b>  |  |
| 5 TFR-LU2C-01    | 2C Lucent Fan Tray<br>(COMCODE: 106382336 / 109198341) <b>LUCENT 2C</b>  |  |
| 6 TFR-LU4A-01    | 4A Lucent Fan Tray<br>(COMCODE: 106526742) <b>LUCENT 4A</b>  |  |
| 7 TFR-LU4G-01    | 4G Lucent Fan Tray<br>(COMCODE: 107378036) <b>LUCENT 4G</b>  |  |
| 8 TFR-LU4B-01    | 4B Lucent Fan Tray<br>(COMCODE: 106527005) <b>LUCENT 4B</b>  |  |
| 9 TFR-COM6F-01   | 6F CommScope Fan Tray<br>(HECI: VAUCADYxxx) <b>COMMSCOPE 6F</b>  |  |
| 10 TFR-SLCAPW-01 | McLean/Reltec SLC APW<br>(Tray # UJB17H48S22) <b>SLC APW</b>   |  |



| REPAIR<br>VENDOR #   | REFURBISHMENT DESCRIPTION<br>(New TAG Fans, New TAG Alarm Boards<br>are Installed - New Switches, Connectors<br>& Hardware are Supplied As Needed) | PICTURE   |
|----------------------|--|---|
| 11<br>TFR-LS2000-02  | Litespan 2000 HV PDFA<br>(Tray # 509-0000-086 &<br>509-0000-163)<br><br><b>LS2000<br/>HV PDFA</b>  |    |
| 12<br>TFR-LS2000-44  | Litespan 2000 DFA<br>(Tray # 500-1100-400)<br><br><b>LS2000<br/>DFA</b>  |   |
| 13<br>TFR-UMC1000-06 | Tellabs UMC1000,<br>6 Fan Tray<br>(Tray # 0310-1716 or<br>8650-0414)<br><br><b>UMC1000<br/>(6 FAN)</b>   |  |
| 14<br>TFR-UMC1000-08 | Tellabs UMC1000,<br>8 Fan Tray<br>(Tray # 4195091)<br><br><b>UMC1000<br/>(8 FAN)</b>   |  |
| 15<br>TFR-UMC1000-10 | Tellabs UMC1000,<br>10 Fan Tray<br>(Tray F10 # 0310-1716)<br><br><b>UMC1000<br/>(10 FAN)</b>   |  |
| 16<br>TFR-FA400-04   | Marconi Fan Tray FA400<br>Master Fan Unit<br>(P/N# FA-400-175-001)<br><br><b>MARCONI<br/>MASTER<br/>FA400</b>                                      |  |
| 17<br>TFR-CN5140-01  | Ciena 5140 Fan Tray<br><br><b>CIENA<br/>5140</b>   |  |
| 18<br>TFR-114A-01    | 114A Lucent Control Unit for<br>Heat Exchanger Fans<br>(COMCODE: 106894934)<br><br><b>LUCENT<br/>114A</b>  |  |
| 19<br>TFR-MARC6-01   | Marconi/Degree ECU<br>HX Fan Control Unit<br>(P/N# ECU-05682,<br>105683, 105684)<br><br><b>MARCONI<br/>ECU</b>                                     |  |