


OSP Cabinet Replacement Fans

PN # TF-SLC5-01
SLC5 Cabinet - 2B Fan Unit
48 Volt Replacement Fan
w/ 3 Wire Plug



*(Equiv. to KS22501L5A,
Used in Lucent OSP 2B fan units)*



Application:

TAG's PN # TF-SLC5-01 replaces defective 3 Wire 48 Volt Fans in Lucent OSP 2B Fan Units. *(Equiv. to KS22501L5A)*

2B FAN UNIT w/ DEFECTIVE FANS



Ordering Information:

TF-SLC5-01 **SLC5 Cabinet - 2B Fan Unit 48 Volt Replacement Fan**
w/ 3 Wire Plug
(Equiv. to KS22501L5A, Used in Lucent OSP 2B fan units)

VZ ID #
1132 1557

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax: (856) 768-7645

Telecom Assistance Group