Frame Cords for Lumen / CenturyLink

PART#	DESCRIPTION
ST400300S-02 ST400300S-06	463A PLUG to ALLIGATOR CLIPS
	2' MAT # 1157465 6' MAT # 1157466
400300FP	"FROGGER" w/ IN-LINE PROTECTION
	* Good * Bad *
	MAT # 1157486
400300S-4	PROTECTOR to (4) ALLIGATOR CLIPS
	MAT # 1157485
400526A-02	526A PLUG to ALLIGATOR CLIPS
	MAT # 1157469
	ST400300S-02 ST400300S-06 400300FP

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

Telephone: (856) 753-8585 Fax: (856) 768-7645

Frame Cords for Lumen / CenturyLink

FEATURES / APPLICATION	PART#	DESCRIPTION
Dual Push Pins (310 MDF) to Alligator Clips, (3')	400426	DUAL PUSH PINS to ALLIGATOR CLIPS
 Used to short the tip and ring or to ground the tip and/or ri Plugs to recessed terminals on 310 series connectors Equivalent to P2FM 	ng	
452A plug to Alligator Clina (21)	400430	MAT # 1157484 453A PLUG to ALLIGATOR CLIPS
453A plug to Alligator Clips, (3')		453A PLUG 10 ALLIGATOR CLIPS
 Used to short the tip and ring or to ground the tip and/or ri Plugs to recessed terminals on 300 series connectors (exception) 	•	
Equivalent to P2EF		MAT # 1157481
Bantam to 800 DSX, (6')	408210	BANTAM to 800 DSX
Test equipment access to 800 DSX		
		MAT # 1157181
310 to 800 DSX, (12')	408310-12	310 to 800 DSX
Test equipment access to 800 DSX		
		MAT # 1183104
800 DSX Looping Plug	408800LD	800 DSX LOOPING PLUG
Loops both directions		408800LD MAT # 1157470
800 DSX Terminating Plug	408800TP-1	800 DSX TERMINATING PLUG
Available in 100 ohm		MAT # 1335085
CONTRACTOR OF THE CONTRACTOR O		

Copyright © 2024 by Telecom Assistance Group, Inc.

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 datasheets\CenturyLink\Frame_Cords_CLK_r01.dsf (05/14/24) **Telephone:** (856) 753-8585

Fax: (856) 768-7645


good line.

"Frogger" Protector Test Cord, (20')



2. Insert "Bad" (red) plug into bad line for temporary restoration.





Application:

TAG's Temporary Restoral Cord (400300FP) allows you to add protection back to the telephone line when testing. TAG's test cord features a built-in protector socket that accepts any 5-pin protector module. A 5-pin module with the same specifications as the line you are testing on must be inserted before the test cord can function. Once inserted, the cord will now function and protection has been restored to the line.

In the event of a power or lightning strike, TAG's 400300FP can save thousands of dollars by eliminating dangers that can destroy expensive equipment or possibly harm a technician. One plug is Green "GOOD" & the other plug is Red "BAD". When the repair is made, the circuit can be identified as to which pair is good or bad.

Ordering Information:

400300FP "Frogger" Protector Test Cord - (20')

<u>Lumen/CLK MAT #</u> 1157486

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax: (856) 768-7645