# **OSP Cabinet Replacement Fans & Alarm Control Boards**



## "LS2000 Heat Exchanger"

#### PN # TF-LS2000-03

48 Volt Replacement Heat Exchanger for **Litespan 2000 Cabinet Heat Stack** 

w/ 3 Unterminated Leads -Red (+48 Return), Black (-48V), Blue (Sensor) Includes (3) Butt Splices

CenturyLink MAT # 1359389



**LS2000 CABINET (OUTSIDE VIEW)** 


### "DFA Fans & Alarm Control Boards"

PN # TF-LS2000-44 Litespan 2000 DFA Fan Kit

CenturyLink MAT # 1445489

#### Kit includes:

- (4) <u>NEW</u> 48V Fans w/ Guard Grills includes (16) plastic rivets & (4) zip ties
- (1) NEW Wiring Harness w/ 12 Wire Plug



KIT SHOWN INSTALLED IN EXISTING DFA FAN TRAY \*

\*(DFA FAN TRAY IS NOT INCLUDED)

NEW Alarm Control Boards are also available, order # TFC-DFA-01, MAT # 1458948



use in existing DFA, DC Fan Assembly 500-1100-XXX

Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order # TF-LS2000-04 (CenturyLink MAT # 1445620)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax: (856) 768-7645

Telecom Assistance Group