

Litespan 2000 HV PDFA Fan Tray (TFR-LS2000-02)

STEP 1

Part Number

SAP Material Code: Manufacturer Part Nbr: Part Description:

HECI:

STEP 2

After STEP 1 and STEP 2:
 Manufacturer Part Nbr and Part Description will be auto populated.
 Note: Disregard inactive or deleted in Part Description

Ship Details

STEP 3

From Address: From City: From State:

From Zip: Contact Name: Contact Nbr:

Serial Nbr: Equipment Error: Tracking Number:

Vendor Name: Vendor Nbr:

STEP 4:
 Click "Create" to Generate a Shipping Label

SHIPPING LABEL



OLD TRAY
 Litespan 2000 HV PDFA Fan Tray
 (FAN TRAY# 509-0000-086)




Litespan 2000 HV PDFA Fan Tray (TFR-LS2000-02)

OLD TRAY (EMPTY)



**# TFC-PDFA-01
NEW Alarm Control Board**



**# TF-LS2000-02 (QTY OF 3)
48V Fan Litespan 2000 High Velocity PDFA
w/ 3 Wire Connector**



NEW FAN 1

NEW FAN 2

NEW FAN 3

**COMPLETED REFURB
WITH ALL NEW FANS,
NEW ALARM CONTROL
BOARD &
WARRANTY LABEL**



Tray Refurbished By:	PN: TFR-LS2000-02
 TAG INC. Telecom Assistance Group, Inc. 856-753-8585 www.tagcords.com	SN: <u>148191</u>
	WARRANTY EXP DATE: <u>07-15-2024</u>

For questions or additional information please contact:

Rob Schramm
Regional Sales Manager
(o) 856-753-8585
(c) 856-701-6727
(e) rob@tagcords.com