

DMS-100 Dual-Scroll Blower Replacement Unit



► **NEW Drop-in Replacement**

**DMS-100 DUAL-SCROLL
REPLACEMENT BLOWERS**


(used in
NT9X950 "w/ hanging blowers"
(replaces # A0383325 & A0381714))

(Commonly found in
DPCC / LIM / ENET bays)



w/ (2) CONNECTORS:

(1) 4 PIN PLUG
&
(1) 3 PIN PLUG*

*(includes adapter cable,
TFCS-DMSMCL3)



plug adapter
cable here



**NT9X950
HAS (3) BLOWER UNITS PER BAY**

Ordering Information:

TF-DMSMCL-02

DMS-100 Dual-Scroll Blower Replacement Unit

AT&T PID #

ATT.200008095

w/ (1) 4 pin plug & (1) 3 pin plug

*includes (1) 3 pin adapter cable (# TFCS-DMSMCL3) (used in NT9X950 "w/ hanging blowers"
(replaces # A0383325 & A0381714)) (commonly found in DPCC / LIM / ENET bays)*

TFC-DMSAPW-3

Alarm Board for DMS LIM/ENET Blower - (not shown)

ATT.200009341

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax : (856) 768-7645

Telecom Assistance Group