
## **OSP Cabinet Replacement Fans & Alarm Control Boards**



\*(this fan is also available with Faston Connectors, order # TF-LU2C-02F, AT&T PID # ATT.200009333)

## "Lucent 2C"

## PN # TF-LU2C


48 Volt Replacement Fan for Lucent <u>2C</u> Fan Tray

w/ 3 Wire Plug

(Equiv. to KS22501L5A)

NEW Alarm Control Boards are also available, order # TFC-LU2BC-01, AT&T PID # ATT.200006513





LUCENT <u>2C</u> FAN TRAY IN MESA TYPE CABINET (fan tray is not included)



AIRFLOW DIRECTION POINTS UP (SIDE VIEW)

$\sim$			4 *
()ro	lerina	Informati	tion:
0.0			

TF-LU2C

TF-LU2C-02F

TFC-LU2BC-01

48V Fan for Lucent <u>2C</u> Fan Tray w/ 3 Wire Plug

AT&T PID # ATT.200002997

(Equiv. to KS22501L5A)

48V Fan for Lucent <u>2C</u> Fan Tray w/ 3 Leads & Faston

ATT.200009333

Connectors - (not shown)

Alarm Control Board for Lucent 2B & 2C Fan Trays

ATT.200006513

TFCS-2BPWRY-01 Power Cable "Y" for Lucent 2B & 2C Fan Trays

ATT.200006909

w/ 1 Male Connector to Female "Y", (1') - (not shown)

A11.20000690

TFCS-2BRS-08 Remote Sensing Daisy Chain Cable for Lucent

ATT.200006910

2B & 2C Fan Trays w/ 2 Wires & Connectors, (8') - (not shown)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax: (856) 768-7645

Telecom Assistance Group