

# OSP Cabinet Replacement Fans & Alarm Control Boards

## "Lucent 4A / 4B"

### PN # TF-SLC201



48 Volt Replacement Fan for  
SLC 2000 4A / 4B Fan Trays

w/ 5 Wire Plug

*(Equiv. to KS23912L6)*

*(80 Type Cabinet,  
SLC 2000 Tray - Internal)*

**SLC 2000 EQUIPMENT -  
4B FAN UNIT w/ (2) FANS**  
*(fan tray is not included)*



**NEW** Alarm Control Boards  
are also available,  
order #TFC-LU4-01,  
AT&T PID # ATT.200004557



### Ordering Information:

**TF-SLC201** 48V Fan w/ 5 Wire Plug for SLC 2000 4A / 4B Fan Trays  
*(Equiv. to KS23912L6) (80 Type Cabinet, SLC 2000 Tray - Internal)*

**TFC-LU4-01** Alarm Control Board Replacement for 4A/4B,  
4G/SLC 2000 Trays & 114A Control Units  
*(control board only - customer supplied fan trays / 114A housing)*

### AT&T PID #

ATT.200002993

ATT.200004557

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585

Fax : (856) 768-7645

**Telecom Assistance Group**