


Power Cable Replacement (TYCO CPS 6000 to ALP-448 HX Controller)



Purcell ALP-448 Cabinet HX



Ordering Information:

TFCS-PURVPWR-05

Power Cable Replacement for OE # HX 100008379, (two conductor) from TYCO CPS 6000 to Purcell ALP-448 Cabinet HX Controller, (5')

TFCS-PURVPWR-06

Power Cable Replacement for OE # HX 100008379, (two conductor) from TYCO CPS 6000 to Purcell ALP-448 Cabinet HX Controller, (6')

AT&T PID

ATT.200008096

ATT.200008229

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645