# **TAG Refurbishing - Lorain, V15F50/P Recitifer**

- Replace Fan & Necessary Components

#### **Repair Benefits:**

- Save Engineering \$\$ on new OSP equipment
- Ease of Replacement "Swap out"





### **Ordering Information:**

TRR-LV15F50-01

Rectifier TAG, LORAIN V15F50/P Rectifier TRR-LV15F50-01

V15F50/P RECTIFIER REFURBISHMENTS
ARE NOW AVAILABLE IN AT&T UPFRONT

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com


Telecom Assistance Group

Telephone: (856) 753-8585

Fax: (856) 768-7645

## Rectifier TAG, LORAIN V15F50/P Rectifier TRR-LV15F50-01





### upFront Tool

### Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print (3) three copies, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.



AT&T is a registered ® trademark