


# TAG Refurbishing - Lorain, V100BR Ring Generator

- Replace Fans & Necessary Components

## Repair Benefits:

- Save Engineering \$\$ on new OSP equipment
- Ease of Replacement "Swap out"



**HECI / CLEI:  
PRPUAF01AA**



## Ordering Information:

TRR-RGV100BR Ring Generator, LORAIN V100BR Ring Generator  
TAG Refurbishment TRR-RGV100BR

**BEFORE ORDERING, PLEASE CALL or EMAIL:  
856-753-8585 - [custsvcs@tagcords.com](mailto:custsvcs@tagcords.com)**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)  
**Telecom Assistance Group**

Telephone: (856) 753-8585  
Fax: (856) 768-7645