

Identifying Alcatel 7330 VRAD Fan Units




(3FE 24322 (XXXX) (HECI:VAPQAFZFAA,
VAPQAFZFAB, VAPQAFZFAC,
VAPQAFZFAD)



TAG Refurbishment, Alcatel 7330 VRAD Fan Unit (TFR-ALC7330-01)

OLD FAN UNIT (EMPTY)



**# TF-ALC7330-4
(4) 48V Fans w/ Guard Grills &
Wiring Harness w/ Hardwired DB15F**



**COMPLETED REFURB
WITH ALL NEW FANS,
WIRING HARNESS &
WARRANTY LABEL**



Tray Refurbished By:

PN: TFR-ALC7330-01



SN: 148193

WARRANTY
EXP DATE: 01-13-2023

*For questions or additional
information please contact:*

Rob Schramm
Regional Sales Manager
(o) 856-753-8585
(c) 856-701-6727
(e) rob@tagcords.com

TAG Refurbishment, Alcatel 7330 VRAD Fan Unit (TFR-ALC7330-01)



OLD TRAY
7330 VRAD Fan Tray
 (3FE 24322 (XXXX) (HECI:VAPQAFZFAA, VAPQAFZFAB, VAPQAFZFAC, VAPQAFZFAD)

Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set: Fan Assembly, Alcatel 7330 VRAD (HECI: VAPQAFZFxx) (3FE 24322 (XXXX) TAG Refurbishment TFR-ALC7330-01

Supplier: TAG INC. TAG is chosen as the supplier

Serial Number:

Asset Tag:

Ship to Address: 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 [Lookup](#)

Manager ATTUID (Who Owns Equipment): RS781D [Lookup](#)

Contact ATTUID (To Be Called if Problem): RS781D

Problem Category: Other

Description of Problem: Refurbish Alcatel 7330 VRAD fan tray

Manufacturer: Alcatel

Model #: 7330 VRAD fan tray

[Create Ticket](#) [Repair Menu](#) Create Ticket will issue repair # and shipping label

[Main Menu](#) | [Order Material](#) | [My Orders](#) | [My Approvals](#) | [My Material](#) | [Order Status](#) | [Reports](#) | [Profile](#) | [View Cart](#) | [Help](#) | [Logout](#) | © AT&T Inc.

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580

Repair Tag: R735580  **SAMPLE**

Truck Route (GA005A): 

Return To: SOPHIA ADAMS
 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044

Telephone: 4044996083

Product Description: NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

Serial Number

Asset Tag

RMA

Problem Category: Intermittent Problem

Description of Problem: THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SHIP MATERIAL TO:

Stage for RYDER pickup and delivery to Team Alliance Drop Code: GA005A

Print Date: 2/19/2016 8:00:08 AM
 Supplier Website for More Detail: <http://www.attsuppliers.com>