


Identifying Lucent 2A Fan Units

2 versions of the 2A (blue or tan)




TAG Refurbishment, Lucent 2A Fan Unit (TFR-LU2A-01)


OLD FAN UNIT (EMPTY)



NEW Alarm Control Board



**# TF-LU2A (QTY OF 3)
48V Fan for Lucent 2A Fan Tray**



NEW FAN 1




NEW FAN 2



NEW FAN 3

**COMPLETED REFURB
WITH ALL NEW FANS,
NEW ALARM CONTROL BOARD &
WARRANTY LABEL**




Tray Refurbished By: **PN: TFR-LU2A-01**
TAG INC. SN: 148194
Telecom Assistance Group, Inc. WARRANTY
856-753-8585 EXP DATE: 03-22-2024
www.tagcords.com

*For questions or additional
information please contact:*

Rob Schramm
Regional Sales Manager
(o) 856-753-8585
(c) 856-701-6727
(e) rob@tagcords.com

TAG Refurbishment, Lucent 2A Fan Unit (TFR-LU2A-01)

OLD TRAY, Lucent 2A Fan Unit (blue)



OLD TRAY, Lucent 2A Fan Unit (tan)



TAG REFURBISHED FAN TRAYS - FOLLOW YOUR REPAIR PROCESS THROUGH UPFRONT

Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

Tool/Test Set	Fan Assembly, 2A Lucent Fan Tray TAG Refurbishment TFR-LU2A-01		1
Supplier	TAG INC.		
Serial Number	<input type="text"/>		
Asset Tag	<input type="text"/>		
Ship to Address	1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044		Lookup
Manager ATTUID (Who Owns Equipment)	RS781D	Lookup	
Contact ATTUID (To Be Called if Problem)	RS781D		
Problem Category	Other		
Description of Problem	<input style="width: 100%;" type="text" value="Refurbish Lucent 2A fan tray"/>		
Manufacturer	Lucent		
Model #	2A fan tray		
<input style="border: 2px solid red; padding: 5px;" type="button" value="Create Ticket"/> <input type="button" value="Repair Menu"/>			

[Main Menu](#) | [Order Material](#) | [My Orders](#) | [My Approvals](#) | [My Material](#) | [Order Status](#) | [Reports](#) | [Profile](#) | [View Cart](#) | [Help](#) | [Logout](#) | © AT&T Inc.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

TAG is chosen as the supplier

Create Ticket will issue repair # and shipping label

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

