

Identifying Lucent 4A Fan Units

(COMCODE: 106526742)



TAG Refurbishment, Lucent 4A Fan Unit (TFR-LU4A-01)

OLD FAN UNIT (EMPTY)



TFC-LU4-01
NEW Alarm Control Board

TF-SLC201 (QTY OF 2)
48V Fan for SLC 2000 4A Fan Unit
w/ 5 Wire Plug



NEW FAN 1



NEW FAN 2

COMPLETED REFURB
WITH ALL NEW FANS,
NEW ALARM CONTROL BOARD &
WARRANTY LABEL



Tray Refurbished By: PN: TFR-LU4A-01
SN: 148192
WARRANTY
EXP DATE: 01-13-2023

TAG INC.
Telecom Assistance Group, Inc.
856-753-8585
www.tagcords.com

For questions or additional information please contact:

Rob Schramm
Regional Sales Manager
(o) 856-753-8585
(c) 856-701-6727
(e) rob@tagcords.com

TAG Refurbishment, Lucent 4A Fan Unit (TFR-LU4A-01)

OLD TRAY
Lucent 4A Fan Unit
(COMCODE: 106526742)



TAG REFURBISHED FAN TRAYS - FOLLOW YOUR REPAIR PROCESS THROUGH UPFRONT

Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

TAG is chosen as the supplier

Create Ticket will issue repair # and shipping label

Tool/Test Set: Fan Assembly, 4A Lucent Fan Tray (COMCODE: 106526742) TAG Refurbishment TFR-LU4A-01
 Supplier: TAG INC.
 Serial Number:
 Asset Tag:
 Ship to Address: 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 [Lookup](#)
 Manager ATTUID (Who Owns Equipment): RS781D [Lookup](#)
 Contact ATTUID (To Be Called if Problem): RS781D
 Problem Category: Other
 Description of Problem: Refurbish Lucent 4A fan tray
 Manufacturer: Lucent
 Model #: 4A fan tray

Main Menu | Order Material | My Orders | My Approvals | My Material | Order Status | Reports | Profile | View Cart | Help | Logout | © AT&T Inc.

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580

Repair Tag: R735580  **SAMPLE**
 Truck Route (GA005A): 
 Return To: SOPHIA ADAMS
 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044
 Telephone: 4044996083
 Product Description: NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below
 Serial Number:
 Asset Tag:
 RMA:
 Problem Category: Intermittent Problem
 Description of Problem: THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SHIP MATERIAL TO:

Stage for RYDER pickup and delivery to Team Alliance Drop Code: GA005A

Print Date: 2/19/2016 8:00:08 AM
 Supplier Website for More Detail: http://www.attsuppliers.com