




# TAG Refurbishment, Marconi / Degree-C ECU HX Fan Control Unit

(P/N ECU-05682,  
105683, 105684)



## Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set: Fan Assembly, Marconi/Degree C Fan Tray ECU HX Fan Control Unit (P/N# ECU-05682, 105683, 105684) TAG Refurbishment TFR-MARC6-01

Supplier: TAG INC. (TAG is chosen as the supplier)

Serial Number: [ ]

Asset Tag: [ ]

Ship to Address: 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 [Lookup](#)

Manager ATTUID (Who Owns Equipment): RS781D [Lookup](#)

Contact ATTUID (To Be Called if Problem): RS781D

Problem Category: Other

Description of Problem: Refurbish Marconi Degree C ECU HX Fan Control Unit

Manufacturer: Marconi

Model #: Degree C

[Create Ticket](#) [Repair Menu](#)

Main Menu | Order Material | My Orders | My Approvals | My Material | Order Status | Reports | Profile | View Cart | Help | Logout | © AT&T Inc.

Create Ticket will issue repair # and shipping label

## upFront Tool

### Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

