


# TAG Refurbishing - Eltek Valere, V1000A Rectifier

- Replace Fans & Necessary Components

## Repair Benefits:

- Save Engineering \$\$ on new OSP equipment
- Ease of Replacement  
“Swap out”



## Ordering Information:

TRR-VAL20A-01    Rectifier TAG, ELTEK VALERE V1000A Rectifier  
TRR-VAL20A-01  
48V, 20 AMP, HECI / CLEI: PBP2DCTBAA

V1000A RECTIFIER REFURBISHMENTS  
ARE NOW AVAILABLE IN AT&T UPFRONT

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)  
Telecom Assistance Group

Telephone: (856) 753-8585  
Fax : (856) 768-7645

# Rectifier TAG, ELTEK VALERE V1000A Rectifier TRR-VAL20A-01



## Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. It will be the address that the unit will be returned to. Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

**TAG's Fan Assembly refurbishment item is chosen from the dropdown menu**

Tool/Test Set	Rectifier TAG, ELTEK VALERE V1000A Rectifier TRR-VAL20A-01
Supplier	TAG INC.
Serial Number	
Asset Tag	
Ship to Address	1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 <a href="#">Lookup</a>
Manager ATTUID (Who Owns Equipment)	RS781D <a href="#">Lookup</a>
Contact ATTUID (To Be Called if Problem)	RS781D
Problem Category	Other
Description of Problem	FAILED UNIT
Manufacturer	ELTEK VALERE
Model #	V1000A
<input type="button" value="Create Ticket"/> <input type="button" value="Repair Menu"/>	

**TAG is chosen as the supplier**

**Create Ticket will issue repair # and shipping label**

Main Menu | Order Material | My Orders | My Approvals | My Material | Order Status | Reports | Profile | View Cart | Help | Logout | © AT&T Inc.

## upFront Tool

### Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580	
Repair Tag:	R735580
Truck Route (GA005A):	
Return To	SOPHIA ADAMS 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 30044
Telephone	4044996083
Product Description	NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below
Serial Number	123456
Asset Tag	abcde####
RMA	
Problem Category	Intermittent Problem
Description of Problem THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.	
<b>SHIP MATERIAL TO:</b> <b>TAG, Inc. (Telecom Assistance Group)</b> <b>150 Cooper Rd. Suite F-15</b> <b>West Berlin, NJ 08091</b>	
<small>Print Date: 7/19/2024 1:39:32 PM          Supplier Website for More Detail: <a href="http://www.attsuppliers.com">http://www.attsuppliers.com</a></small>	

**SAMPLE**